

BUILDING INFORMATION

Facility	TROY		
Building Name	SECTION/COMMUNICATION BUILDI	Number of Floors	1
Client Code	BNRR	Approx Floor Are	
Construction Date	UNKNOWN	Bldg Const Type	STEEL FRAME
Original Owner	BNRR	Floor Const Matl	CONCRETE
Building Number		Floor Covering	NONE
Bldg Address	YAAK AVENUE	Roofing Material	METAL
Latitude	48.46056	Roof Construction	METAL
Longitude	115.88779	Ceiling Materia	METAL
Bldg Status	IN-PLACE	Exterior Wall	METAL
Existing Plan	FIELD SKETCH	Interior Wall	METAL



INSPECTION HISTORY

Start Date	End Date	Project Name	Project Number	Inspector Name
10/20/1994	10/20/1994	INITIAL INSPECTION		
3/13/2001	3/13/2001	REINSPECTION	5243.01	DAVID WELCH
4/16/2001	4/16/2001	REMOVAL	5243.02	DAVID WELCH
11/6/2001	11/6/2001	VERMICULITE INSPECTION	5410.001-2	CLYDE CORKILL



Back

Samples	Insulation	Uses	Next	Previous
Notices	Renovations	Owners	Add Building	Delete Building

BUILDING INFORMATION

Facility	TROY		
Building Name	STORAGE (EAST)	Number of Floors	1
Client Code	BNRR	Approx Floor Are	96
Construction Date	1950S	Bldg Const Type	MASONRY
Original Owner	BNRR	Floor Const Matl	METAL & WOOD
Building Number		Floor Covering	NONE
Bldg Address	YAAK AVENUE	Roofing Material	METAL
Latitude	48.46023	Roof Construction	METAL
Longitude	115.88772	Ceiling Materia	METAL
Bldg Status	IN-PLACE	Exterior Wall	METAL
Existing Plan	FIELD SKETCH	Interior Wall	WOOD & METAL



INSPECTION HISTORY

Start Date	End Date	Project Name	Project Number	Inspector Name
10/20/1994	10/20/1994	INITIAL INSPECTION		
9/22/1997	9/22/1997	REINSPECTION	2662.07	JANET WILSON
1/15/2001	1/15/2001	REINSPECTION	5053.01	DAVID WELCH
11/6/2001	11/6/2001	VERMICULITE INSPECTION	5410.001-2	CLYDE CORKILL



Back

Samples	Insulation	Uses	Next	Previous
Notices	Renovations	Owners	Add Building	Delete Building

BUILDING INFORMATION

BUILDING INFORMATION REPORT

Facility:	TROY	Building Name:	SECTION/COMMUNICATION BUILDING
City:	TROY, MT	Building Number:	

Construction Date: UNKNOWN

Original Owner:	BNRR	Bldg Const Type:	STEEL FRAME
Location Marker:	YAAK AVENUE	Floor Const Matl:	CONCRETE
Latitude:	48.46056	Floor Covering:	NONE
Longitude:	115.88779	Roofing:	METAL
Bldg Status:	IN-PLACE	Roof Construction:	METAL
Existing Plans:	FIELD SKETCH	Ceiling:	METAL
Number of Floors:	1	Exterior Wall:	METAL
Approx Floor Area:		Interior Wall:	METAL

BUILDING INSULATION

HVAC Code	HVAC Insulation
	FIBERGLASS

BUILDING USES

Use	Percent of Total Area
STORAGE	100
OFFICES	100

BUILDING RENOVATIONS

BUILDING OWNERS

INSPECTION HISTORY

Start Date	End Date	Project Name	Project No.	Inspector Name	Inspection Reason
10/20/1994	10/20/1994	INITIAL INSPECTION			
3/13/2001	3/13/2001	REINSPECTION	5243.01	DAVID WELCH	
11/6/2001	11/6/2001	VERMICULITE INSPECTI	5410.001-2	CLYDE CORKILL	SYSTEM-WIDE INSPECTION
4/16/2001	4/16/2001	REMOVAL	5243.02	DAVID WELCH	

HOMOGENEOUS AREAS

Number	Description	General Area	ACM Type	Percent
TRMT-SHB-001A	VERMICULITE	W END OF ATTIC	ACTINOLITE	0.03
TRMT-SHB-001A	VERMICULITE	W END OF ATTIC	WINCHITE	0.31
TRMT-SHB-002A	VERMICULITE	CENTRAL ATTIC	WINCHITE	0.11

Friday, August 19, 2011

BUILDING INFORMATION REPORT

Facility:	TROY	Building Name:	SECTION/COMMUNICATION BUILDING	
City:	TROY, MT	Building Number:		
TRMT-SHB-003A	VERMICULITE	EAST END OF ATTIC	ACTINOLITE	0.11
TROY-SS-01	TRANSITE	CEILING	CHRYSTILE	35
TROY-SS-701	VERMICULITE	ABOVE CEILING	NON-ACM	
TROY-SS-702	VERMICULITE	ABOVE CEILING	NON-ACM	
TROY-SS-703	VERMICULITE	ABOVE CEILING	NON-ACM	

Friday, August 19, 2011

Homogeneous Physical Assessment Report

Location

State: MT Facility: TROY

Building Name: SECTION/COMMUNICATION BUIL

Homogeneous Area Description

Description: VERMICULITE
General Area: W END OF ATTIC
Category: MISC
Color: TAN
Material Status: REMOVED

Class: FRI.
Amount: 469 S.F.
Date Removed: 4/16/2001

Damage Assessment

Condition Assessment: N/A
Percent Damage:
Extent Damage:
Physical Damage:
Water Damage:
Deterioration:
Vibration:

Exposure Factors

Visible:
Accessibility:
Barriers:
Activity:
Ventilation:
Air Erosion:

Sample Result

Sample Number: TRMT-SHB-001A
Asbestos Type: WINCHITE

Sample Date: 3/13/2001
Percent: 0.31

Sample Result

Sample Number: TRMT-SHB-001A
Asbestos Type: ACTINOLITE

Sample Date: 3/13/2001
Percent: 0.03

Signed:		AHERA No.:
		State Certification No.:
Signed:		AHERA No.:
		State Certification No.:

Homogeneous Physical Assessment Report

Location

State: MT Facility: TROY

Building Name: SECTION/COMMUNICATION BUIL

Homogeneous Area Description

Description: VERMICULITE

General Area: CENTRAL ATTIC

Category: MISC

Color: TAN

Material Status: REMOVED

Class: FRI.

Amount: 469 S.F.

Date Removed: 4/16/2001

Damage Assessment

Condition Assessment: N/A

Percent Damage:

Extent Damage:

Physical Damage:

Water Damage:

Deterioration:

Vibration:

Exposure Factors

Visible:

Accessibility:

Barriers:

Activity:

Ventilation:

Air Erosion:

Sample Result

Sample Number: TRMT-SHB-002A

Asbestos Type: WINCHITE

Sample Date: 3/13/2001

Percent: 0.11

Signed:		AHERA No.:
		State Certification No.:
Signed:		AHERA No.:
		State Certification No.:

Homogeneous Physical Assessment Report

Location

State: MT Facility: TROY

Building Name: SECTION/COMMUNICATION BUIL

Homogeneous Area Description

Description:	VERMICULITE		
General Area:	EAST END OF ATTIC		
Category:	MISC	Class:	FRI.
Color:	TAN	Amount:	469 S.F.
Material Status:	REMOVED	Date Removed:	4/16/2001

Damage Assessment

Condition Assessment: N/A
Percent Damage:
Extent Damage:
Physical Damage:
Water Damage:
Deterioration:
Vibration:

Exposure Factors

Visible:
Accessibility:
Barriers:
Activity:
Ventilation:
Air Erosion:

Sample Result

Sample Number: TRMT-SHB-003A
Asbestos Type: ACTINOLITE

Sample Date: 3/13/2001
Percent: 0.11

Signed:		AHERA No.:
		State Certification No.:
Signed:		AHERA No.:
		State Certification No.:

Homogeneous Physical Assessment Report

Location

State: MT Facility: TROY

Building Name: SECTION/COMMUNICATION BUIL

Homogeneous Area Description

Description: TRANSITE

General Area: CEILING

Category: MISC

Color: GREY

Material Status: REMOVED

Class: N.F. II

Amount: 88 S.F.

Date Removed: 4/26/2001

Damage Assessment

Condition Assessment: DAMAGED

Percent Damage: <10%

Extent Damage:

Physical Damage: LIGHT

Water Damage: LIGHT

Deterioration: LIGHT

Vibration: LIGHT

Exposure Factors

Visible: >10%

Accessibility: ACCESSIBLE

Barriers: NO

Activity: LIGHT

Ventilation: NO

Air Erosion: NO

Sample Result

Sample Number: TROY-SS-01

Asbestos Type: CHRYSOTILE

Sample Date: 10/20/1994

Percent: 35

Signed:		AHERA No.:
		State Certification No.:
Signed:		AHERA No.:
		State Certification No.:

State: MT**City: TROY****Facility: TROY****Building Name: SECTION/COMMUNICATION BUILDING****Latitude: 48.46056****Longitude: 115.88779****Inspection Date: 10/20/1994**

Sample Number	Description	General Area	Class	Amount	Units	Condition	Asbestos Type	Status
TROY-SS-01	TRANSITE	CEILING	N.F. II	88	S.F.	DAMAGED	CHRYSTILE	REMOVED 4/26/2001

Inspection Date: 12/26/2000

Sample Number	Description	General Area	Class	Amount	Units	Condition	Asbestos Type	Status
TROY-SS-701	VERMICULITE	ABOVE CEILING	FRI.	469	S.F.	DAMAGED	NON-ACM	REMOVED 4/16/2001
TROY-SS-702	VERMICULITE	ABOVE CEILING	FRI.	469	S.F.	DAMAGED	NON-ACM	REMOVED 4/16/2001
TROY-SS-703	VERMICULITE	ABOVE CEILING	FRI.	469	S.F.	DAMAGED	NON-ACM	REMOVED 4/16/2001

Inspection Date: 3/13/2001

Sample Number	Description	General Area	Class	Amount	Units	Condition	Asbestos Type	Status
TRMT-SHB-001A	VERMICULITE	W END OF ATTIC	FRI.	469	S.F.	N/A	WINCHITE	REMOVED 4/16/2001
TRMT-SHB-001A	VERMICULITE	W END OF ATTIC	FRI.	469	S.F.	N/A	ACTINOLITE	REMOVED 4/16/2001
TRMT-SHB-002A	VERMICULITE	CENTRAL ATTIC	FRI.	469	S.F.	N/A	WINCHITE	REMOVED 4/16/2001
TRMT-SHB-003A	VERMICULITE	EAST END OF ATTIC	FRI.	469	S.F.	N/A	ACTINOLITE	REMOVED 4/16/2001

BUILDING INFORMATION REPORT

Facility:	TROY	Building Name:	STORAGE (EAST)
City:	TROY, MT	Building Number:	

Construction Date: 1950S

Original Owner:	BNRR	Bldg Const Type:	MASONRY
Location Marker:	YAAK AVENUE	Floor Const Matl:	METAL & WOOD
Latitude:	48.46023	Floor Covering:	NONE
Longitude:	115.88772	Roofing:	METAL
Bldg Status:	IN-PLACE	Roof Construction:	METAL
Existing Plans:	FIELD SKETCH	Ceiling:	METAL
Number of Floors:	1	Exterior Wall:	METAL
Approx Floor Area:	96	Interior Wall:	WOOD & METAL

BUILDING INSULATION

HVAC Code	HVAC Insulation
NONE	NONE

BUILDING USES

Use	Percent of Total Area
STORAGE	100

BUILDING RENOVATIONS

BUILDING OWNERS

INSPECTION HISTORY

Start Date	End Date	Project Name	Project No.	Inspector Name	Inspection Reason
10/20/1994	10/20/1994	INITIAL INSPECTION			
9/22/1997	9/22/1997	REINSPECTION	2662.07	JANET WILSON	
1/15/2001	1/15/2001	REINSPECTION	5053.01	DAVID WELCH	
11/6/2001	11/6/2001	VERMICULITE INSPECTI	5410.001-2	CLYDE CORKILL	SYSTEM-WIDE INSPECTION

Friday, August 19, 2011

BUILDING INFORMATION REPORT

Facility:	TROY	Building Name:	STORAGE (WEST)
City:	TROY, MT	Building Number:	

Construction Date: 1950S

Original Owner: BNRR

Bldg Const Type:

Location Marker: YAAK AVENUE

Floor Const Matl: METAL & WOOD

Latitude: 48.46015

Floor Covering: NONE

Longitude: 115.88783

Roofing: METAL

Bldg Status: IN-PLACE

Roof Construction: METAL

Existing Plans: FIELD SKETCH

Ceiling: METAL

Number of Floors: 1

Exterior Wall: METAL

Approx Floor Area: 91

Interior Wall: WOOD & METAL

BUILDING INSULATION

BUILDING USES

BUILDING RENOVATIONS

BUILDING OWNERS

INSPECTION HISTORY

Start Date	End Date	Project Name	Project No.	Inspector Name	Inspection Reason
10/20/1994	10/20/1994	INITIAL INSPECTION			
11/6/2001	11/6/2001	VERMICULITE INSPECTI	5410.001-2	CLYDE CORKILL	SYSTEM-WIDE INSPECTION

HOMOGENEOUS AREAS

Number	Description	General Area	ACM Type	Percent
TRMT-SWS-000	NO SUSPECT MATERIALS	N/A	N/A	

Friday, August 19, 2011